## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.











Fig. 3



BEST AVAILABLE COPY 504 \$70. V S Fig. 5








Fig. 8





Fig. 9








Fig. 11











Fig. 15










Fig. 18

Express Mail Label EV308901746US "Tile Lighting Methods and Systems" By: George G. Mueller et al. Attorney Docket No. C1104-7127.30






Fig. 19









Fig. 22

Express Mail Label EV308901746US "Tile Lighting Methods and Systems" By: George G. Mueller et al. Attorney Docket No. C1104-7127.30









Fig. 24





									 r		ı	г
2600	2620	Position										
	2618	Other Sys.								-	_	
	2614	Intensity	0-100							-		
	2612	Color Range	0-16000	0-16000	0-16000	0-16000	0-16000	0-16000				
	2610 Þ	Lit Position	Poly001	Poly001	Poly 002	Polv 003	Poly004	Poly 005				
	2608	Position	(1, 3, 7)	(1, 3, 7)	(1, 3, 7)	(0,0,0)	(0,0,0)	(0,0,0)				
	2604	Time	Ţl	T2	Т3	Т1	T2	Т3				TN
	2602	Light System	LS001	LS001	LS001	LS002	LS002	LS002				TS00N


Fig. 26















3200









Fig. 34







Express Mail Label EV308901746US "Tile Lighting Methods and Systems" By: George G. Mueller et al. Attorney Docket No. C1104-7127.30




Fig. 37

Fig. 38




Fig. 39






Fig. 40








Fig. 42






Fig. 43





Snap-in Bottom Mount





Fig. 46






Fig. 47

Express Mail Label EV308901746US "Tile Lighting Methods and Systems" By: George G. Mueller et al. Attorney Docket No. C1104-7127.30






Fig. 48








Fig. 51








Fig. 52
















Fig. 57




Fig. 58




Fig. 59








Fig. 60












Fig. 65




Fig. 66




Fig. 67




Fig. 68

